WWS100i Beeper Settings and Power Off Timeout barcodes in the manual aren't working

Jason - 2017-07-06 - WWS100i Pocket

The programming barcodes in the manual for the Beeper Settings and the Power Off Timeout have changed in firmware version SM3-c-1.30 and newer. Print out the two attached sheets for the updated settings.

Attachments

- WWS100iBeeperSettings.pdf (7.05 KB)
- WWS100iPowerOffTimeout.pdf (9.72 KB)