MobileAsset v7: Wasp-branded WDT92, DR2, and DR3 mobile devices require (or use up) a non-Wasp mobile device license

Scott Leonard - 2019-08-16 - in Mobile Computers

Symptom

Although MobileAsset v7 should not require a separate mobile device license for Wasp-branded devices, when you use the Wasp-branded WDT92, DR2, or DR3 mobile devices with MobileAsset v7:

1. The device returns a message "No available licenses".
   or
2. The device uses up one of your already-entered non-Wasp mobile device licenses.

Cause

The WDT92, DR2, and DR3 devices were released after MobileAsset v7, so MobileAsset

is not aware of those device types.

Resolution

The following batch file updates MobileAsset to recognize the WDT92, DR2, and DR3.

Download, save, and extract the following zip file on the server (the PC that holds the database):
http://dl.waspbarcode.com/kb/ma/v7/mav7-new-devices.zip

Inside the extracted folder, double-click the UpdateDB.bat file. The change takes effect immediately. Note: The zip file must be extracted first. If UpdateDB.bat is run from within the zip file, it will not work.

Note: For Enterprise edition customers whose SQL instance is not WASPDBEXPRESS, first edit the script.wql file with a text editor so that the server= line contains the proper server and instance (if any).

Related Pages

- MobileAsset v7 installation on WDT92 fails
- Mobile Device User Manuals, Programming Reference Guides, Quick Reference Guides, Quick Start Guides (multiple models)