

[Knowledgebase](#) > [Hardware](#) > [Mobile Computers](#) > [DR6/ DR5 mobile device: scan engine appears to work, but no data \(or partial data\) is entered into app fields](#)

DR6/ DR5 mobile device: scan engine appears to work, but no data (or partial data) is entered into app fields

Scott Leonard - 2025-04-10 - [Mobile Computers](#)

Symptom

On a DR5 or DR6 mobile devices, using the scan buttons with the scan engine appears to work (the device beeps for a successful scan) but no data is entered into the app field (e.g. Asset Tag or Item Number). One user reported that a phrase "Sample Room" was being auto-entered into multiple fields.

When scanning into the ScanService app, data appears as expected. The Scan Parsing feature was not enabled in AssetCloud and InventoryCloud. Using the camera produces data as expected.

Problem

Erroneous data has been cached in the Autofill service.

Solution

Disable Autofill.

- DR5: Settings, Privacy, Advanced
- DR6: Settings, Privacy

then "Autofill service from Google": Slide the button "Use Autofill with Google" to the left to turn off this service.

Note

In at least one instance, after scanning began producing expected data in the apps, turning Autofill back on still allowed correct scans in apps, while other Autofill functionality was enabled elsewhere on the device.