Enable Telepen symbology barcodes on WCS3900, WLR8900, WLR8950 scanners

Internal User - 2023-01-20 - WCS3900/3905/3950

This article applies to WCS3900, WLR8900, WLR8950 scanners.

The Telepen symbology is disabled by default. To enable:

Download and print this document:
https://dl.waspbarcode.com/kb/scanner/telepen.pdf

Scan the Enable Telepen barcode.