WWS650: scanning into Notepad in Windows 11, only short bursts of characters are produced

Scott Leonard - 2023-09-11 - Scanners

We have observed an issue with the WWS650 scanner where scanning into the Notepad application in Windows 11 produces only 2 or 4 characters of the barcode with each squeeze of the trigger.

This is a problem with the Notepad program, and does not happen with other programs such as Microsoft Word or Notepad++.