

Wasp

BARCODE TECHNOLOGIES

Portal > Knowledgebase > Discontinued Products > Hardware > 300 Thermal Label Printer :
Operation : I changed the printer's ribbon and now the barcodes are smudged with imprecise lines. The scanner can't read them.

300 Thermal Label Printer : Operation : I changed the printer's ribbon and now the barcodes are smudged with imprecise lines. The scanner can't read them.

Internal User - 2017-04-10 - in Hardware

Try turning down the print darkness in the print driver's settings from wherever it is currently set to a value of about 5 and then try it again.