



[Knowledgebase](#) > [Hardware](#) > [Scanners](#) > [WDI4600](#) > [WDI4600: do not send the last character \(check digit\) from a UPC-A barcode](#)

WDI4600: do not send the last character (check digit) from a UPC-A barcode

Scott Leonard - 2023-01-19 - [WDI4600](#)

The WDI4600's Product Reference Guide and Quick Reference Guide can be downloaded here if necessary:

<https://support.waspbarcode.com/kb/articles/833>

You will need to scan either from PDF page 92 on the screen, or from printed page 82.

Scan "Enter/Exit Programming Mode" at the top of the page.

Scan "UPC-A Check Character Transmission = Don't Send".

Scan "Enter/Exit Programming Mode" again.

Wait a moment while the scanner resets.