

Wasp

BARCODE TECHNOLOGIES

[Portal](#) > [Knowledgebase](#) > [Hardware](#) > [WDT2200 - Cannot log out of the WDT2200 unit.](#)

WDT2200 - Cannot log out of the WDT2200 unit.

Tom Tate - 2019-09-24 - in Hardware

Reset your WDT 2200:

1. Switch off the unit while at the same time press and hold the following 3 keys:

CMD+ left arrow+switch on

A menu should now show up on the screen that says:

<<START MENU>>

1. SUPERVISOR
2. WARM START
3. COLD START

2. Press 3. COLD START

A new screen appears stating:

WILL DELETE ALL
DATA !
Are you Sure ? _
1=YES/0=NO

3. Press 1 for YES

Now the screen should say:

WDT2200 V1.20
MEM 2560 kb
>

Resend the program & data from the PC to the WDT2200:

1. Make sure your WDT2200 is linked to the PC.
2. Go to Mobile Devices/PDT/WDT2200/Setup device.
3. Select Auto Detect COM Port Settings (please wait a few moments until these is completed).
4. Then create the PDT database (At this stage, select All for the filter records) and send data from the PC to the PDT.