



[Knowledgebase](#) > [Hardware](#) > [Scanners](#) > [WWS100i Pocket](#) > [WWS100i Beeper Settings and Power Off Timeout barcodes in the manual aren't working](#)

WWS100i Beeper Settings and Power Off Timeout barcodes in the manual aren't working

Jason - 2017-07-06 - [WWS100i Pocket](#)

The programming barcodes in the manual for the Beeper Settings and the Power Off Timeout have changed in firmware version SM3-c-1.30 and newer. Print out the two attached sheets for the updated settings.

Attachments

- [WWS100iBeeperSettings.pdf \(7.05 KB\)](#)
- [WWS100iPowerOffTimeout.pdf \(9.72 KB\)](#)