

# Wasp

## BARCODE TECHNOLOGIES

Portal > Knowledgebase > Hardware > Scanners > WWS100i Pocket > WWS100i Beeper Settings and Power Off Timeout barcodes in the manual aren't working

---

### WWS100i Beeper Settings and Power Off Timeout barcodes in the manual aren't working

Jason Whitmer - 2017-07-06 - in WWS100i Pocket

The programming barcodes in the manual for the Beeper Settings and the Power Off Timeout have changed in firmware version SM3-c-1.30 and newer. Print out the two attached sheets for the updated settings.

#### Attachments

---

- [WWS100iBeeperSettings.pdf \[7.05 KB\]](#)
- [WWS100iPowerOffTimeout.pdf \[9.72 KB\]](#)