MASIS BARCODE TECHNOLOGIES

Portal > Knowledgebase > Hardware > Time Clocks > HD300 - The clock will not read my HID cards

HD300 - The clock will not read my HID cards

Jason Whitmer - 2017-04-10 - in Time Clocks

The HD300 will read both 26 and 34 bit cards. If your card does not work automatically, than that means that it is unsupported. This is likely due to the card being encrypted, as this is not supported, or the card does not meet the HID card standard.