



WASP PROTECT

[Portal](#) > [Knowledgebase](#) > [Hardware](#) > [Scanners](#) > [WWS550i](#) > [WWS550i scanner: hardware reset button](#)

WWS550i scanner: hardware reset button

Scott Kircher - 2018-04-12 - in WWS550i

Sometimes strange behavior from a WWS550i scanner can be corrected by using the reset button. This button is inside the housing.

The picture below describes how to find it: Holding the scanner with the aperture/lens pointing away from you, on the right side there is an oval hole. Insert a straightened paper clip or similar implement at the end of the hole toward the scanner lens. Press the button for about a second, then release (you will feel a click when the button is pressed). Then try scanning again.



Related Pages

- [Pairing Wasp's Bluetooth scanner models: WWS100i, WWS150i, WWS250i, WWS550i](#)
- [WWS550i: Manual and Quick Start Guide](#)