



# WASP PROTECT

Portal > Knowledgebase > Discontinued Products > Hardware > 300 Thermal Label Printer :  
Operation : I changed the printer's ribbon and now the barcodes are smudged with  
imprecise lines. The scanner can't read them.

---

300 Thermal Label Printer : Operation : I changed the  
printer's ribbon and now the barcodes are smudged with  
imprecise lines. The scanner can't read them.

Internal User - 2017-04-10 - in Hardware

Try turning down the print darkness in the print driver's settings from wherever it is  
currently set to a value of about 5 and then try it again.