

Wasp

BARCODE TECHNOLOGIES

Portal > Knowledgebase > Hardware > Printers > Labeler v7: slowness printing March 2023

Labeler v7: slowness printing March 2023

Scott Leonard - 2024-01-08 - in Printers

Starting March 2023, Wasp Tech Support received a few reports of slowness printing from Labeler to various label printers. We continue to investigate the issue. In the meantime, we have found that a third-party driver by Loftware/Nice may allow printing without delay to Wasp WPL printers.

Download page:

<https://drivers.loftware.com/brand/wasp>

During installation, only a limited number of models are listed, so we recommend choosing WPL-305 when prompted.

Printer Installation Wizard

Select Printer

Please select the printer that you would like to install.


Software
NiceLabel

- WASP WPL-205
- WASP WPL-303
- WASP WPL-305
- WASP WPL-604
- WASP WPL-606
- WASP WPL-610

Show all printers

Exit < Previous **Next >**

In Printer Preferences, specify the width and height of your labels (use a ruler if you're not sure).



After installation, if you need to run the driver installer again, here's the path:

C:\NiceLabel Printer Drivers\wasp\PrnInst.exe

You can also manually install drivers, specifying this path & file:

C:\NiceLabel Printer Drivers\wasp\WASP.inf