

# Wasp

## BARCODE TECHNOLOGIES

[Portal](#) > [Knowledgebase](#) > [Software](#) > [Labeler](#) > [Version 6](#) > [My Dymo Labelwriter 330 will not print more than one label at a time.](#)

---

### My Dymo Labelwriter 330 will not print more than one label at a time.

Sicaro Burnett - 2017-04-10 - in Version 6

Labeler v5 (and later versions) have a check box in the Tools > Options dialog, which allows you to tell Labeler that the "Printer does not support multiple copies." When this option is enabled, Labeler will manage the printer directly, sending multiple "one-page" print jobs to the printer, instead of a single, multi-page job.