

Scanner is decoding a plus sign between characters in Code 39 barcodes

Max Holden - 2017-04-10 - [Hardware](#)

Go into your programming guide and setup the scanner to read full ascii code 39, this will resolve the problem.